


Site Visit to Standard Chlorine 05/07/02 - photos taken with digital camera by John Malleck, EPA Region 2




Looking east at naphthalene processing area



Looking east towards lagoon area in distance





Southern Drainage ditch - note the wood coming through the liner.



Looking east towards naphthalene processing area.



Looking east towards lagoon area (on far side of second fence).



Cove off of southern drainage ditch located in between Buildings 3 and 4.



Southern drainage ditch looking from center of site towards the confluence of the upgradient portion with the western end of drainage ditch.



Looking northeast across gravel IRM for chromium exposure.



Southern drainage ditch. Note brown seeps in white deposit.



Southern drainage ditch where the upgradient portion conflues with western portion and opens up into wetlands open water.



A building in old naphthalene processing area.



Debris in southern drainage ditch.



Southern drainage ditch looking east towards Hackensack River.



Eastern end of southern drainage ditch looking west.



Southern drainage ditch.



South outfall into Hackensack River.



Duck in Hackensack River just downstream of south outfall.



Warning sign on property at bank of Hackensack River.



Canada Goose in lagoon.




Standard Chlorine from Hackensack River.



Pier upstream of Standard Chlorine. Off Diamond Shamrock property.



Standard Chlorine from Hackensack River.



Turning buoy downstream from Standard Chlorine. Site of popular fishing spot.


**Standard Chlorine Site Visit 05/07/02 - Photos taken by
Kristin Dobinson, EPA Region 2**



Fishermen just upstream of Standard Chlorine site.




Boat washed up on the banks of the Hackensack River, bordering the Standard Chlorine property.



Northern outfall



Makeshift dock at popular downstream fishing spot.



Makeshift dock at popular downstream fishing spot.